

## Localization of a sewage pipe at the former location of the Berlin Wall.


Schönholz, 8.4.2004, dipole-dipole profile (a=0.5 m), SIP256C, f=1.25 Hz, Res2Dinv

Problems:

1. High interference voltage level due to 50 m distant DC-fed S-Bahn line.
2. Poor coupling of the electrodes due to asphalt and cobblestone tracks in the ground and concrete foundations of the former barriers.

Conclusion: Unlike the resistance, the IP phase clearly indicates the position of the sewage pipe.

### Betrag /Ohmm



### Phase /Grad

